



# Tech Info Library

## Macintosh Portable: Replacement Part for Weak Plastic Handle

Article Created: 5 April 1991

Article Last Reviewed: 29 July 1992

Article Last Updated:

TOPIC -----

The plastic handle (630-5071) and the display housing assembly (652-0605) on my Macintosh Portable are very weak and keep breaking. Are there any solutions to this problem?

DISCUSSION -----

Some Macintosh Portable computers manufactured before July 1990 have weak plastic handles. A replacement handle is available. Contact your authorized Apple dealer for more information.

Copyright 1991, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7836