



# Tech Info Library

## PowerBook 2300: Memory Test Error Message at Startup (5/96)

Article Created: 9 April 1996

Article Reviewed/Updated: 9 May 1996

TOPIC -----

I am getting a strange error message on my PowerBook 2300 computer at startup. It says, "The built-in memory test has detected a problem. Please contact a service technician for assistance." What does this mean?

DISCUSSION -----

Issue

-----

This problem is the result of an out-of-spec RAM card. The failure was first noticed with some third party 12 MB RAM cards at Apple's manufacturing facility in Cork, Ireland. A resistor change to that third party card corrected the problem.

Resolution

-----

You should have the RAM card replaced by the manufacturer.

Copyright 1996, Apple Computer, Inc.

Keywords: kpbook,hts

=====

This information is from the Apple Technical Information Library.

19960513 15:50:59.00

Tech Info Library Article Number: 19772