



Tech Info Library

Powerbook 2300: Dock Issue W/Third-Party Ethernet Cards (5/96)

Article Created: 29 May 1996

TOPIC -----

I just purchased a Macintosh Powerbook 2300 (Duo) series computer. When I put it in my Duo Dock Ethernet does not work. It works fine with my PowerBook Duo 230 computer. What could be wrong?

DISCUSSION -----

It is possible that some non-Apple (third-party) Ethernet NuBus cards installed in a Apple Duo Docking stations will not work with the PowerBook 2300 series computers even if they work with all other PowerBook Duo computers.

In contrast, the Apple Ethernet NB card (M0417LL/B) works with all models of PowerBook Duo computers including the 2300 series. It is possible that some third-party Ethernet board manufacturers may not have followed the Apple design specifications closely enough, resulting in some problems with the 2300 series.

If you have a non-Apple Ethernet card in your Duo Docking station that is not working with a PowerBook 2300 series computer, you should contact the vendor of that NuBus Ethernet board/card for more information concerning compatibility.

Copyright 1996, Apple Computer, Inc.

Keywords: kpbook,hts

=====

This information is from the Apple Technical Information Library.

19960530 07:07:47.00

Tech Info Library Article Number: 19880