



Tech Info Library

PowerBook 3400: Incompatible With FM Radio Extension (3/97)

Article Created: 3 March 1997

Article Reviewed/Updated: 4 March 1997

TOPIC -----

The extension "FM Radio Extension" causes a crash on PowerBook 3400 series computers if it is present when the computer starts up.

DISCUSSION -----

The FM Radio Extension is installed by the TV/FM Software v1.5.3 (or 1.5.4) which comes with the TV/FM Tuner card. There is no reason that this software should be installed on a PowerBook computer since the TV/FM Tuner card cannot be installed in a PowerBook computer.

If you think you may have installed this extension and your PowerBook computer is now crashing while starting up, follow these steps:

Step 1

Restart the computer with the Shift key held down*.

Step 2

After the computer has started up, open the System Folder

Step 3

Open the Extensions folder

Step 4

Remove the "FM Radio Extension" from the Extensions folder.

Step 5

Restart the computer. The PowerBook will restart normally after removing the extension.

* NOTE: The Extensions Manager (accessed by holding down space bar at startup) will not recognize the FM Radio Extension, so you must start up with the Shift

key held down which turns off all extensions.

This article was published in the Information Alley on 7 March 1997.

Article Change History:

04 Mar 1997 - Added keyword.

Copyright 1997, Apple Computer, Inc.

Keywords: kpbook,ksts,kalley

=====

This information is from the Apple Technical Information Library.

ArticleID: TECHINFO-0021046

19970305 09:45:40.00

Tech Info Library Article Number: 21046