



Tech Info Library

PowerBook 500 Series: Indicators Of A Blown Fuse (6/94)

Article Created: 23 June 1994

TOPIC -----

What symptoms would be generated should the replaceable fuse on the PowerBook 500 series computer fail?

DISCUSSION -----

When the power on button is pressed the screen would flicker as if the unit was starting it's normal power on process the go blank again. No startup chime would be heard regardless of power source, battery or AC power.

Support Information Services
Copyright 1994, Apple Computer, Inc

Keywords: kpbook

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15671