



# Tech Info Library

## PowerBook: Problems with Express Modem & Prodigy (3/95)

Article Created: 12 January 1994

Article Reviewed/Updated: 31 March 1995

TOPIC -----

This article is to clear up two common problems PowerBook owners with Express Modems may report when using Prodigy.

DISCUSSION -----

Prodigy Error CT#24 - Can't communicate with the modem.

-----  
This problem usually indicates that the customer is using an older version of the Express Modem software. The solution is to use Express Modem 1.1.2 software or later. (2.0 is the current version)

Prodigy Error CT#8 - Noisy phone line.

-----  
The problem lies in the 'connect' message that Prodigy is expecting once a connection has been established. It has nothing to do with a noisy phone line.

Due to the ATW2 default setting within the Express Modem, it reports a full connection message:

```
CARRIER 2400
PROTOCOL :NONE
COMPRESSION: NONE
CONNECT 2400
```

Prodigy expects just "CONNECT 2400" and will disconnect immediately.

To solve the problem, the modem setup string within the CONFIG.SM file needs to be modified. ":ATW0X1" needs to be appended to the modem\_str line. For example:

```
modem_str:3615,0,,2400,+++,CR,CRLF,1,4,6,N,30,50,3,6,32,N,N,,?,
S0,,S2,,,,S6,S7,,S9,S10,,S12,,,,,,,,,V1,Q0,,,X1,,D,T,P,X1,H,,,,,,,,,
OK,0,CONNECT,1,RING,2,NO CARRIER,3,ERROR,4,CONNECT 1200,5,
NO DIALTONE,6,BUSY,7,NO ANSWER,8,CONNECT 2400,10,,,,,,,,, :ATW0X1
```

The W0 command disables Progress codes 40 through 80 and the X1 command restricts the Express Modem in using only result codes 0 through 4 and 8. Refer

to the Express Modem User's guide, pages 120-121 for complete details.

Article Change History:

31 Mar 1995 - Reviewed for technical accuracy.

09 Jun 1994 - Made correction to modem string.

Support Information Services

Copyright 1994-95, Apple Computer, Inc.

Keywords: kpbook

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 14433