



Tech Info Library

SCSI Probe: Not Responding After Adding SCSI Drive (6/93)

Article Created: 1 July 1993

TOPIC -----

When I try to run SCSI Probe, I briefly get the wristwatch and the desktop blinks but no SCSI device table comes up. This happened after I added another SCSI hard disk. Before that everything worked fine.

DISCUSSION -----

You probably have conflicting SCSI device numbers. Check that every SCSI device has a unique number and that none of the external devices have number 0 or 7, which are reserved for the internal hard disk and the Macintosh itself, respectively. Typically, there is a rotary dial on SCSI devices for setting the device number.

Copyright 1993, Apple Computer, Inc

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12497