



Tech Info Library

TokenTalk NB Card: Compatibility of RasterOps Video Card

This article last reviewed: 17 October 1990

TOPIC -----

I have been having compatibility problems with RasterOps video cards and Apple's TokenTalk NB Card.

DISCUSSION -----

RasterOps identified and corrected some problems with their 224/724 cards. The problems occurred on Macintoshes with a 224/724 card and TokenTalk NB Card.

- 1) No video on the 224/724 card at powerup.
- 2) Selecting 24 bits/pixel on the 224/724 card causes pixels to change color under the cursor (and at random on the startup screen).
- 3) Zones and servers appear and disappear.
- 4) In all of the above cases, eventually a bus error (ID=1, sometimes ID=28) system bomb occurs.

The fixes are hardware rework. All finished goods and cards shipped since early May 1990 should contain this fix. Customers with problems should contact the RasterOps Technical Support department.

Copyright 1990 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 6228