



Tech Info Library

Kensington Turbo Mouse: Using with System 6.0.5 Requires Patch

Article Created: 18 April 1991

Article Last Reviewed:

Article Last Updated:

TOPIC -----

My Macintosh IIX (running System 6.0.5.) freezes when the system is starting up. The problem is intermittent and happens only when the mouse--a Turbo Mouse from Kensington--is plugged in. (We have swapped out the mouse and the keyboard.)

DISCUSSION -----

The Turbo mouse has a problem with System 6.0.5. Kensington has a patch for this. For contact information, search the Tech Info Library under "Kensington".

Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7517