



Tech Info Library

MacDraw II, 1.1: ImageWriter LQ Printing Problem

This article last reviewed: 7 September 1989

There is a known problem when using a Macintosh SE/30 with System 6.0.3, ImageWriter Driver 2.0, ImageWriter LQ, and MacDraw II 1.1.

When trying to print on computer paper with a reduction of 66%, the first half of the document is skipped (the printer starts to print from the middle of the document in the middle of the page).

However, If you place a small line (it can even be a point) on the file and print the document, everything will print as normal.
Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 4359