



Tech Info Library

DAL 1.2 & Avatar Coax Card: Driver to use for CUT/DFT Modes

Article Created: 20 August 1991

Article Change History

07/10/92 - REVIEWED

- For technical accuracy

TOPIC -----

I can't connect to DAL 1.2 on an IBM mainframe using an Avatar coax card in CUT mode.

DISCUSSION -----

DAL 1.2 requires driver release 3.2 or later to work in CUT mode with the Avatar coax card. To run in DFT mode, use driver release 3.3 or later.
Copyright 1991, Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8839