



# Tech Info Library

## HyperCard 2.0: LaserWriter Driver 5.2 Print Problem (11/94)

Article Created: 01 March 1991

Article Reviewed/Updated: 07 November 1994

TOPIC -----

I have been trying to resolve a HyperCard 2.0 printing problem. My system includes System 6.0.5, Finder 6.1.5, LaserWriter Version 5.2, AppleTalk driver version 53, and no INITs.

I'm unable to print cards from a stack that I have developed. When I try to "Print Card" from the File menu, I get a message "Processing Job" that stays on the screen indefinitely. The printer still thinks it is connected to this job, even after I cancel printing, so I have to restart the printer.

Oddly enough, this stack does print to a QMS PS2200 Laser Printer.

DISCUSSION -----

We were able to reproduce the problem with the stack you sent. However, using LaserWriter driver version 6.x the card printed fine. Try upgrading to newer drivers; that may well solve the problem.

Article Change History:

07 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-94, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 6642