



# Tech Info Library

## MegaPhone: Type 11 Error With GeoPort Software (2/97)

Article Created: 3 February 1997

TOPIC -----

If the Telephone Manager is turned off on a Macintosh Performa computer which has an internal GeoPort modem, Megaphone fails with a type 11 error when it is launched. Why?

DISCUSSION -----

This issue is unique to the GeoPort software. When a Macintosh Performa 6400/200 computer with the Global Village software was tested, the dialog states that the Telephone Lib file could not be found, and exits from the application.

Cypress Research has been notified and they will fix it in an upcoming version of MegaPhone.

The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number.

Copyright 1997, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

ArticleID: TECHINFO-0020906

19970204 08:34:06.00

Tech Info Library Article Number: 20906