



Tech Info Library

Macintosh Performa 6400, 6360: Why Apple Video Player? (3/97)

Article Created: 5 March 1997

TOPIC -----

I have a Macintosh Performa 6360 or 6400 series computer. There is an application available under my Apple menu named Apple Video Player. When I select it, it indicates that the necessary video hardware is missing. Should I have gotten something else with my computer?

DISCUSSION -----

No. The Apple Video Player software is provided so as to easily support the Apple Video System, Apple TV/Video System, or Apple TV/FM Radio System (which requires the Apple Video System). These are available as options that can be added to your computer system.

If the computer you are using does not have the necessary hardware installed, Apple Video Player software will present the error message you described.

You may get a similar error message if you add the Apple TV Tuner card or Apple TV/FM Radio System without having the Apple Video System card properly installed.

Copyright 1997, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

ArticleID: TECHINFO-0021076

19970306 08:53:07.00

Tech Info Library Article Number: 21076