



# Tech Info Library

## Power Macintosh: Compatibility Issue with COPYright (6/94)

Article Created: 16 June 1994

TOPIC -----

This article provides a workaround for the problem of COPYright not working with a Power Macintosh or a Power Macintosh Card.

DISCUSSION -----

Here's how to make COPYright work with Power Macintosh:

- Start with COPYright Control version 1.0.4 or 1.0.5
- Open COPYright Control with ResEdit.
- Open "fVER" resources
- Duplicate fVER ID -4039
- Select the new resource and Choose "Get Resource Info" from the Resource Menu
- Renumber the resource to -4038
- Rename the resource to "7.1.4f0" (change the 3 to a 4)
- Save and close
- Reboot.

This information is provided by Management Science Associates, Inc. CSG Technologies Division. Revised versions of COPYright or COPYright PRO will also resolve this problem. Contact the vendor for more information.

To locate a vendor's address and phone number, use the vendor name as a search string.

Support Information Services  
Copyright 1994, Apple Computer, Inc.

Keywords: kcompat

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15629