



# Tech Info Library

## System 7.5: 8•24GC Card Compatibility (12/95)

Article Created: 10 October 1994

Article Reviewed/Updated: 8 December 1995

TOPIC -----

I have a Macintosh IIci, 20MB of RAM, and an 8•24 GC card.

I have upgraded from System Software 7.1 to 7.5. The computer has been running fine, but since upgrading, I get a bus error when starting up. If I use the Extensions Manager to turn off everything but the 8•24 GC software, I still get a bus error.

DISCUSSION -----

The 8•24 GC video card's acceleration software is incompatible with System Software 7.5, when 32-bit addressing is turned on.

There are a couple of ways to use the 8•24 GC card with System 7.5 installed on your Macintosh computer. The first is to turn off 32-bit addressing. This may not be an ideal solution if the Macintosh has more than 8 MB of RAM installed.

The second choice is to remove the 8•24 GC control panel file. The video card and the Macintosh are functional after removing this control panel. However, you cannot use the accelerated graphics feature when the control panel is removed.

### Article Change History:

08 Dec 1995 - Made minor grammatical corrections.

16 May 1995 - Reclassified.

Support Information Services

Copyright 1994-95, Apple Computer, Inc.

Keywords: sys75

=====  
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16469