



Tech Info Library

System 7.5: Quadra 900/950 Sound Input Not Correct (8/95)

Article Created: 29 March 1995

Article Review/Updated: 25 August 1995

TOPIC -----

I have just upgraded to System 7.5 from System 7.1 on my Quadra 900 and 950 computers in our office. Now when I try to record sound from the external RCA jack via the Sound Control Panel, I do not get any sound until we choose the "Internal CD" sound option.

I have installed System 7.5 Update 1.0 and the problem still exists. Why?

DISCUSSION -----

All of the sound input drivers were changed in System 7.5. Unfortunately on a Macintosh Quadra 900 and 950, the "Internal CD" and "External Audio" Sound input options were inadvertently switched. This means that Macintosh Quadra 900 and 950 users need to select the "Internal CD" Sound input option to record audio from external audio sources via the RCA jack. Users who have an internal CD-ROM drive installed need to choose the "External Audio" input option to record audio from their internal CD-ROM drive.

System 7.5 Update 1.0 does not correct the problem. This problem will be corrected in the next update to System 7.5.

Article Change History:

25 Aug 1995 - Made minor corrections.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Keywords: hts,sys75

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17474