



# Tech Info Library

## Audio Volume Read Me (11/95)

Article Created: 14 November 1995

TOPIC -----

This article is the Audio Volume Read Me file.

DISCUSSION -----

This software replaces the Internal Modem Sound extension 1.0 that lets an internal Global Village modem sound play through internal speaker. The Audio Volume extension supports 16-Bit audio capable Performa 5200, 5300, 6200, and 6300 computers with an internal Global Village modem.

Audio Volume Read Me

=====

Important Information About Reinstalling Performa Software

-----

This document tells you how to install the Audio Volume software on your computer after you have reinstalled your Performa software. You need to install the Audio Volume software only after you reinstall Performa software. The Audio Volume software improves sound quality on your computer.

You may want to print this document and keep it with your manuals, since this information may not be in the documentation that came with your computer. After you finish reading this document, choose Quit from the File menu.

Installing the Audio Volume Software

-----

To reinstall Performa software on your computer, follow the instructions in the Macintosh Performa CD booklet, then follow these steps:

- 1) Insert the disk System Backup Disk: Audio Volume Installer into your floppy disk drive.
- 2) Find and double-click the Install Audio Volume icon.
- 3) Follow the instructions that appear on the screen. If you get a message asking you if it's OK to place the Audio Volume software in a folder or to replace an earlier version of the file, click OK. The instructions on the screen let you know when the installer has finished installing the

Audio Volume software.

When your computer restarts, the Audio Volume software is installed on your computer. Keep the disk System Backup Disk: Audio Volume Installer in case you ever need to reinstall Performa software again.

Support Information Services  
Copyright 1995, Apple Computer, Inc.

Keywords: sys75,kppc

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 18926