



Tech Info Library

Energy Saver: Volume Increases After Waking Up (5/96)

Article Created: 14 May 1996

TOPIC-----

When I wake my Power Macintosh 7200/75 computer from sleep, the volume in the Sound control panel is always set to the maximum level. This happens even if I have set the volume to the lowest setting possible prior to putting the computer to sleep. I have a friend who has a Power Macintosh 7200/120 computer and it does not exhibit this symptom. Is there something I can do about this?

DISCUSSION -----

This issue occurs with Power Macintosh 7200 series computers using the Energy Saver control panel version 2.0. It has been resolved with the Energy Saver control panel v2.0.1, which is included in System 7.5 Update 2.0 (System 7.5.3). Your friend's Power Macintosh 7200 series computer came with System 7.5.3 pre-installed, which is why it does not have this problem.

Copyright 1996, Apple Computer, Inc.

Keywords: kcompat, kppc, sys75

=====

This information is from the Apple Technical Information Library.

19960515 15:09:16.00

Tech Info Library Article Number: 19792