



Tech Info Library

800K INIT: Use with System 6.0.3 or Earlier

This article last reviewed: 4 June 1990

TOPIC -----

Was the 800K INIT fix included as part of System 6.0.3 (and later) software? Is it part of the System file? I can't find an INIT file called 800K INIT.

DISCUSSION -----

You do not need to use the 800K INIT with System Software 6.0.4 or later because its equivalent is built in--it's actually part of the System file. However, you do need to install it on Macintosh computers with 800K drives when using System Software 6.0.3 or earlier.
Copyright 1990 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 5712