



Tech Info Library

Macintosh PrintMonitor: Error -1096 Is An AppleTalk ATP Error

Article Created: 5 December 1988
Article Last Reviewed: 6 November 1991
Article Last Updated: 5 December 1988

TOPIC -----

This article describes the -1096 error that may come up when using PrintMonitor.

DISCUSSION -----

If you have been getting the -1096 error when printing under the PrintMonitor, it probably has something to do with your AppleTalk network setup.

Error -1096 is an AppleTalk ATP error that indicates the ATP sendRequest has failed because the retry count has been exceeded. This means that the workstation doing the printing is having a difficult time communicating with the LaserWriter or Print Server.

This suggests some type of AppleTalk network problem, which may be either physical or logical. Check the network for loose connections and proper topology. Also, AppleTalk traffic may be preventing the proper communication between the two devices.

Copyright 1988, 1991 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 3445