



Tech Info Library

Power Macintosh: System 7.5 Update 1.0 and APD 1.1 Issue (5/96)

Article Created: 05 April 1995

Article Reviewed/Updated: 27 May 1996

TOPIC -----

Apple Personal Diagnostics (APD) 1.1 will incorrectly report problems with the logic board on any Power Macintosh with System 7.5 Update 1.0 installed. This problem is fixed in version 1.1.1. All currently shipping APD software is version 1.1.1.

DISCUSSION -----

Beginning April 10, 1995, customers who own a Power Macintosh with System 7.5 Update 1.0 (System 7.5.1) and Apple Personal Diagnostics (APD) 1.1 can order an upgrade to APD 1.1.1 for no charge (no shipping/handling/tax). These customers will be allowed to participate in the existing APD 1.1.1 program.

APD 1.1.1 program details

- Between April 10 and June 30, 1995, customers with a Power Macintosh, System 7.5.1, and APD 1.1 can call the Apple Order Center to order APD 1.1.1 for no charge.
- Customers will be required to provide proof-of-purchase to order.
- This offer is only good in the United States (50 states and DC)
- The software will ship via US Priority Mail.
- Customers can provide an express courier account number to receive the software overnight.

The Tech Info Library article titled "Locating Vendor Information" can help you search for the Apple Order Center's phone number.

Article Change History:

27 May 1996 - Updated for technical accuracy.

Copyright 1995-96, Apple Computer, Inc.

Keywords: kppc,sys75

=====

This information is from the Apple Technical Information Library.

19960528 07:25:21.00

Tech Info Library Article Number: 17523