



Tech Info Library

Run Disk First Aid 7.1.1 or Later Before HD SC Setup (12/93)

Article Created: 4 August 1993

Article Reviewed/Updated: 10 December 1993

TOPIC -----

I received the message "Unable to unmount drive, file may be in use." This happened when I tried to update the hard disk drivers with the new Apple HD SC Setup from the Hardware System Update 2.0 as explained in the ReadMe file. When I rebooted the Macintosh, the hard drive wouldn't mount, and it displayed a flashing question mark.

DISCUSSION -----

Most likely, the system had already run into the problem resolved in the updated drivers. You must run Disk First Aid 7.1.1 or later to ensure that the problem isn't present on the disk prior to updating the drivers with HD SC Setup 7.2. If this order isn't followed, then updating the drivers will fail.

HD SC Setup version 7.2.2 fixes this problem.

Article Change History:

10 December 1993 - Added information about HD SC Setup version 7.2.2.

23 August 1993 - Revised to include Disk First Aid versions later than 7.1.1.

Copyright 1993, Apple Computer, Inc.

Keywords: SUPT, KSTS

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12862