



Tech Info Library

Drive Setup 1.0.5: ReadMe (1/97)

Article Created: 14 June 1996

Article Reviewed/Updated: 20 January 1997

TOPIC -----

This article contains the Read Me file for Drive Setup 1.0.5.

DISCUSSION -----

What's New in Drive Setup 1.0.5?

- * No changes to the SCSI driver.
- * No changes to the IDE driver
- * Updated Drive Setup application to assure that volume creation dates are different when creating multiple partitions on a hard drive. This change fixes a problem where, in rare cases, custom icons may appear incorrectly on a volume with multiple partitions with the same creation dates.

Drive Setup 1.0.5 requires System Software 7.5 or later and is only supported for use with the following systems:

- Power Macintosh systems (including PowerPC-based Performa systems)
- PowerPC-based PowerBook computers*
- Macintosh 580- and 630-series systems and PowerBook 190 series

Drive Setup does not currently support the Macintosh Processor Upgrade. If the upgrade is installed in a Macintosh 580- or 630-series system, use the "601 Processor Upgrade" control panel to turn the card off before using Drive Setup.

* The following computers are in the PowerPC-based PowerBook computer family: PowerBook 5300, 5300c, 5300ce, 5300cs, 2300c, 1400c, and 1400cs. Additionally PowerBook 200 and 500 series computers which have PowerPC upgrade cards installed are included in the PowerPC-based PowerBook computer family.

Article Change History:

20 Jan 1997 - Added details about PPC PowerBook Computers.

Copyright 1996-97, Apple Computer, Inc.

Keywords: supt,kpbook

=====

This information is from the Apple Technical Information Library.

ArticleID: TECHINFO-0020026

19970121 09:59:41.00

Tech Info Library Article Number: 20026