



Tech Info Library

Apple Scanner: Which Scanners Have Termination Problem

Article Created: 13 August 1991

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I understand that some older Apple Scanners have problems with internal termination that needs to be removed. Which scanners have this problem?

DISCUSSION -----

The Apple Scanner has a repair extension in place to cover a termination problem. The scanners covered are:

MODEL	SERIAL NUMBER RANGE
A9M0337	9300249 or below
A9M0337B	9320356 or below
A9M0337J	9330252 or below
A9M9337JA	all units
A9M9337Z	9320000 or below

The information on the procedure for this modification can be located in Macintosh Volume 4, page 5.12 of the Apple Service Technical Procedures. REA code information for warranty reimbursement may be found in the product notices section of the service programs binder.

Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8671