



# Tech Info Library

## AppleCD SC Plus, AppleCD 150: Different Drive Mechanism Designs

Article Created: 14 September 1992

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC -----

In the Technical Procedures, Cross Family Peripherals, AppleCD SC/CD SC Plus/CD 150 section, page 6.2, the introduction paragraph states:

"... the AppleCD 150 contains the same SCSI CD-ROM drive mechanism as the AppleCD SC Plus ..."

Is this correct?

DISCUSSION -----

The two CD mechanisms have the same access time, and so on; however, the drive mechanism designs are different. The AppleCD 150 printed circuit board and headphone board are in different locations on the drive. This change (streamlining) was done to allow the AppleCD 150 to be put into a smaller box. Sony has different part numbers for each mechanism, and they are not interchangeable.

The AppleCD 150 current repair strategy is a "whole unit" exchange. Service Providers should not use an AppleCD SC Plus drive mechanism to repair an AppleCD 150.

For more details, see "Service Notice - AppleCD 150 - 3/92" located on AppleLink. Use this path:

Service & Support  
  Service Notices  
    Service Notices Archives  
      1992 Service Notices  
        January - March, 1992 Service Notices  
Copyright 1992, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10662