



Tech Info Library

Apple IIe Card: Incompatible w/LaserWriter Select 310 (5/93)

Article Created: 25 May 1993

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

When I print from the Apple IIe Card using AppleWorks or Applesoft BASIC, the output from my LaserWriter Select 310 has the top one-third of the page missing.

DISCUSSION -----

This is a known incompatibility between the Apple IIe Card and the LaserWriter Select 310. This occurs with all Macintosh models that accept the IIe Card. This issue is being investigated by the product team.

There is no workaround directly from the IIe Card environment, however ClarisWorks is able to directly read the AppleWorks files. If you have ClarisWorks, follow these steps to print your AppleWorks files:

- 1) Save your AppleWorks files to disk
- 2) Exit the IIe environment
- 3) Open the AppleWorks files in ClarisWorks
- 4) Print the files from the Macintosh environment

For other IIe Card applications, save the document to disk as a text file, and then open the text file from a Macintosh application and print.
Copyright 1993, Apple Computer, Inc.

Keywords: kcompat,supt

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12184