

AppleVision 1710AV: Don't Mix Video Parameter Files (8/96)

Article Created: 28 August 1996
* RESTRICTED: Apple Internal and Support Providers Only * Not For General Public Release
TOPIC
I downloaded the video parameters settings from one AppleVision 1710AV display to another, now I cannot adjust the monitor so that it is within acceptable tolerances. Why?
DISCUSSION
Both video board and CRT for the AppleVision 1710 are factory configured for optimal video resolution and performance. Because of the way the video board and CRT are matched, you should never download video parameter settings from one AppleVision 1710 Display to another. As you have seen, when you mix video parameter settings from one display to another, the result can be a video signal that is so far out of tolerance, that it cannot be adjusted properly.
Copyright 1996, Apple Computer, Inc.
Keywords: hts
mbia information in from the Apple Mechainel Information Tibusus
This information is from the Apple Technical Information Library.
19960829 07:41:38.00

Tech Info Library Article Number: 20341