



Tech Info Library

Color LW 12/600 PS: How To Set Up EPOST Diagnostics (7/96)

Article Created: 11 July 1996

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

How do I enable the built-in EPOST diagnostics on the Color LaserWriter 12/600 PS printer? Sometimes they work and sometimes they do not.

DISCUSSION -----

In order to perform the EPOST diagnostic, the I/O board configuration switch must be in the custom configuration position (to the right), and the green loopback test plug (part #922-1489) installed in the LocalTalk port. If the I/O board configuration switch is in the default position (to the left), the EPOST diagnostic will not work.

Copyright 1996, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960715 07:36:30.00

Tech Info Library Article Number: 20161