



Tech Info Library

LaserWriter IINTX: Replacement ROMs

Article Created: 1 May 1992

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

My customer has a LaserWriter IINTX with ROM numbers 341-0596-A through 341-0603-A installed on the logic board. These ROMs are not listed in the price pages. Which ROM numbers are the correct replacement ROMs?

DISCUSSION -----

The 341-0596-A through 341-0603-A EPROMs were used in the early VADER NTX printers. The newer masked ROMs were cut into production shortly after the LaserWriter IINTX printers started shipping.

The equivalent replacement ROMs are 342-0560 through 342-0567 (they are listed in the LaserWriter II price pages in the Service Programs manual).
Copyright 1992 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10174