



# Tech Info Library

## LaserWriter 16/600 PS: Problems Printing With PacerPrint (1/95)

Article Created: 17 January 1995

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC -----

We have a LaserWriter 16/600 PS and are having trouble printing to it using PacerPrint. Every print job results in the following PostScript error:

```
"error: undefined offendingcommand: sccbatch"  
"flushing: rest of job (to end of file) will be ignored."
```

DISCUSSION -----

The reason that the PostScript errors are occurring is due to the LaserWriter 16/600 PS not having a serial interface. The PostScript operator "sccbatch" returns information about the printer's serial interface (such as baud rate, parity, and so forth) so for the LaserWriter 16/600 PS, this operator returns an "undefined" error. The serial port, as well as LAT protocol support, were not implemented on the LaserWriter 16/600 PS due to the slow performance of serial communications, as well as accounting for a relatively small share of the market.

We will be contacting the folks at Pacer Software to ensure they are aware of this.

Support Information Services  
Copyright 1995, Apple Computer, Inc

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17027