



# Tech Info Library

## Macintosh: TokenTalk & 8•24 Display Card Contention (8/94)

Article Created: 23 July 1991

Article Reviewed/Updated: 22 August 1994

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC -----

Some Macintosh IIcx customers have reported that their computers hang at startup or when using network services like Chooser, or switching between LocalTalk and TokenTalk. The computers have both the TokenTalk NB Card and the Macintosh Display Card 8•24 installed.

Is this a Macintosh IIcx problem, or is the problem with the TokenTalk NB Card and the Macintosh Display Card 8•24?

DISCUSSION -----

The problem is associated with bus contention between the TokenTalk NB Card and the Macintosh Display Card 8•24. To correct the problem, replace the Display Card 8•24 (service part number 661-0678).

Article Change History:

22 Aug 1994 - Revised formatting, corrected service part number for display card.

Support Information Services  
Copyright 1991-94 Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7927