



Tech Info Library

Macintosh IIfx: Problems w/NEC and Third-Party RAM (11/94)

Article Created: 14 May 1991

Article Reviewed/Updated: 10 November 1994

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

After recently upgrading several Macintosh IIfx computers, I'm suddenly experiencing weird lock-ups and crashes with all of them. I've removed all non-Apple INITs, done virus checking, and re-installed the Systems.

DISCUSSION -----

Make sure you aren't using NEC brand RAM. There is a known problem with this brand and you'll need to get the RAM replaced.

In general, if you have third-party RAM, try using Apple RAM to see if it fixes your problems.

Article Change History:

10 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-94, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8448