



Tech Info Library

Macintosh: 1-inch 40MB Drives and Corresponding Carriers

Article Created: 31 October 1991

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

One of our dealers has a Macintosh Classic, and the 1-inch Quantum 40MB drive needs to be replaced. They have three replacement 1-inch Conner 40MB drives, all marked part number 661-0464. When they try to mount these drives in the existing carrier, the screw holes don't match.

DISCUSSION -----

It sounds like the Service Provider may not be using the drive carrier originally installed in the Macintosh Classic.

If the Service Provider follows the directions in the Technical Procedures correctly, both the 1-inch Quantum and 1-inch Connor 40MB drives will fit properly in the same drive carrier. However, if you try to install either 1-inch 40MB drive in a carrier designed for a 3.5-inch drive, the screw holes will not align.

Here is a list of Macintosh models and the carrier part numbers for the 1-inch drives:

Model	Carrier
-----	-----
Macintosh SE	805-0952
Macintosh SE/30	805-0952
Macintosh II	805-0952
Macintosh IIX	805-0952
Macintosh IICx	805-5078
Macintosh IIfx	805-0952
Macintosh IICI	805-5078
Macintosh IISI	805-0980
Macintosh LC	805-0980
Macintosh Classic	805-0950

Copyright 1991, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 9232