



Tech Info Library

Macintosh Hard Disk Test 2.1.1 and 32-Bit Addressing

Article Created: 17 October 1991

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I am experiencing system crashes when running the Macintosh Hard Disk Test 2.1.1 with 32-bit addressing turned on.

DISCUSSION -----

Apple Service Diagnostics tested the Macintosh Hard Disk Test 2.1.1 on all Macintosh models with 32-bit addressing capabilities with 32-bit addressing turned on, and did not experience any system crashes.

We suggest that you try running the Macintosh Hard Disk Test 2.1.1 again with a known good copy of the software. If you still are having system crashes, it may be a hardware problem. Try using the MacTest MP or the appropriate MacTest diagnostic to fully test the Macintosh hardware configuration.

Copyright 1991, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 9235