



# Tech Info Library

## MacTest 7.0: Floppy Disk Error Code (5/93)

Article Created: 12 May 1993

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC -----

I was running MacTest 7.0 on a Macintosh Plus. While the diagnostics were in process, a fail message flashed up on the screen while testing the internal 800K drive. The error code was 40080.0003. I can not track down the error message with the current Service Source CD.

What does this error code signify ?

DISCUSSION -----

The MacTest error 40080.0003 occurred during the internal disk Functional Test. The first two digits of the error indicate the actual test being performed. In this case it's the "Motor Jitter Test". The last digit in the error indicates the actual step of the test which has failed. In this case it's the "Set Third Slowest Speed and Jitter Test" .

If MacTest fails this test the internal disk (motor) is suspect.  
Copyright 1993, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12076