



# Tech Info Library

## Macintosh IIfx: 68040 Accelerators & PDS Slot (7/93)

Article Created: 8 July 1993

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

### TOPIC -----

This article provides information on third-party 68040 accelerator boards for the Macintosh IIfx.

### DISCUSSION -----

Daystar and Fusion Data Systems offer, or are planning to offer, 68040-based acceleration cards for the Macintosh IIfx processor direct slot (PDS). These companies will propose to alter Macintosh IIfx logic board components in order to provide PDS compatibility as a part of their upgrade offerings.

Apple doesn't support any third-party solutions which require alterations to the Macintosh IIfx logic board to make the PDS compatible with their 68040-based acceleration cards.

Logic board modification isn't supported or recommended by Apple and any such modification will void the customer's warranty or AppleCare. The modification will also prevent the board from being repaired in the future by Apple.

At this time, Apple isn't aware of any third party 68040 accelerator boards that are directly compatible with the PDS slot in IIfx logic board.  
Copyright 1993, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12580