



Tech Info Library

Macintosh LC 500 Family: Change in Parts Availability (11/94)

Article Created: 04 November 1994

Article Reviewed/Updated: 14 November 1994

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

There has been a change in Service Strategy for the Macintosh LC 520/550/575, Macintosh TV, and Performa 550/575/576/577 Chassis/Harness Assembly.

The changes will affect part numbers 922-1824, 922-0557, and 922-0767. Part Number 922-1824 is the chassis that supports the Apple SuperDrive, 922-0557 is the chassis that supports the Manual Insert floppy, and 922-0767 supports the AppleCD 300i Plus.

DISCUSSION -----

Until now the chassis assembly contained the Speaker assembly, PCBA Front Panel, FoxConn cable assembly, and EMI shields along with the chassis itself. When one of these parts had failed, the entire chassis would have to be replaced because the individual parts were not available.

Due to recent high demand for the chassis (922-1824, 922-0557), Apple Service is going to break apart the chassis assembly and make the piece parts available. This means that part numbers 922-1824 and 922-0557 will no longer be available as a whole. Service providers can order the following in their places:

922-1825 PCB Assembly, Front Panel
922-1826 Speaker Assy
922-0505 Logic Board Connector and Cable Assembly, LC 520/550*
922-0117 Screw
076-0488 Shield Kit
076-0489 Chassis Kit- (bare chassis)

* Note:

Previously this was know as part number 922-0503 FoxConn cable assembly, CD300i/Auto/Mnl Insrt Flpy.

We can continue to support 922-0767 chassis for the systems with CD300i Plus.

In addition to this, we now can provide additional parts:

922-1825 PCB Assembly, Front Panel
922-1826 Speaker Assy
922-0117 Screw
076-0488 Shield Kit

If a service provider requires a FoxConn assembly or a chassis replacement, they must buy the entire 922-0767. The other parts are available for lower level replacement if they determine that these are the damaged parts within the chassis.

Article Change History:

04 Mar 1997 - Updated with current service part numbers.
14 Nov 1994 - Corrected part number for bare chassis.

Copyright 1994-97, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

ArticleID: TECHINFO-0016686

19970305 09:45:40.00

Tech Info Library Article Number: 16686