



Tech Info Library

Macintosh LC 500 Series: Restarts After Shutdown (11/94)

Article Created: 28 November 1994

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

After replacing the analog board in a Macintosh LC 575, the computer restarts after being shut down. Is this power supply bad also?

DISCUSSION -----

On the Macintosh LC 500 series, the replacement analog boards occasionally come with the test jumper still installed. The jumper is BD11 located on the right hand side, towards the front of the system.

Simply remove the jumper to resolve the restart after shutdown condition.

The Macintosh LC 500 series includes the Macintosh LC 520, Macintosh LC 550, and Macintosh LC 575.

Support Information Services
Copyright 1994, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16803