



Tech Info Library

Macintosh IIcx/IIci: Soldered Battery Replacement (3/95)

Article Created: 31 March 1995

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

We received a Macintosh IIci for service which had a dead battery which was soldered on to the logic board. No part number is listed in the Service Source CD or the Service price pages for a soldered battery.

Is replacing the logic board the only way to get them a new battery?

DISCUSSION -----

Some Macintosh IIcx and IIci logic boards had the battery soldered on. The replacement battery is exactly the same as on a Apple IIgs, part number 742-0009.

Use that battery for any Macintosh IIcx or Macintosh IIci with a soldered battery.

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17485