



# Tech Info Library

## Macintosh Computers Service Guide Vol III: Manual Error

Article Created: 12 April 1995

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC -----

This article documents a manual error in an Apple Service Guide.

DISCUSSION -----

Service Guide - Macintosh Compouters Volume III, July 1994

Page 84 Subject: Port list for PowerBook 520,520c, 540 & 540c

The Printer/Modem port and ADB port identifications are reversed.

Support Information Services  
Copyright 1995, Apple Computer, Inc.

Keywords: kmanerr

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17576