MegaPhone: Update to Speed Doubler v1.0.2 (11/95)

Article Created: 27 November 1995

Article Reviewed/Updated: 30 November 1995

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I am using a Performa 6200 series computer. When I answer the phone, all I hear is a dial tone. Using the Extensions Manager, I have isolated the issue to a conflict with Speed Doubler. What should I do?

DISCUSSION -----

Cypress Research, the makers of MegaPhone, are investigating this issue and recommend that you use the latest version of Speed Doubler, v1.0.2 as of the modification date of this article. However, you may still encounter intermittent difficulties when using MegaPhone.

Contact Connectix and Cypress Research for more information.

The Tech Info Library article titled "Locating Vendor Information" can help you search for Connectix's address and phone number.

Article Change History:
30 Nov 1995 - Changed distribution status.

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: ksts

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 18973