



Tech Info Library

Multiple Scan 20 Display: Rev A vs. Rev B Service Parts (11/95)

Article Created: 28 November 1995

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

This article contains information on determining the revision of service parts for the Multiple Scan 20 Display.

DISCUSSION -----

It is important to determine the revision of Apple Service parts since Rev. A and Rev. B parts are not interchangeable.

Listed below are the visual differences between the revisions. The changes are subtle, so the easiest things to look for in order to differentiate the two apart are mentioned.

Begin_Table

Main Deflection Board

Differences

661-0996 Rev B

FB501 located on the right of heat sink
Capacitor C560 is present

661-0506 Rev A

FB501 located on the left of heat sink
Capacitor C560 not present

Power Supply

661-0508 Rev A

R1610, R1611 Not Present

661-1007 Rev B

R1610, R1611 Present

Microprocessor Control Board

922-0685 Rev A

IS-77AT : Number located on the back of the
board

922-1570 Rev B

IS-7A : Number located on the back of the
board

End_Table

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 18981