



# Tech Info Library

## Multiple Scan 14 Display: Correct Audio Cable Part Numbr (11/95)

Article Created: 28 November 1995

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC -----

I ordered additional audio (sound-out) cables for the Multiple Scan 14 Display. The part the Service Price Pages says to use (922-1781), does not work. There is a plastic ring around the metal probe which prevents the cable from fitting correctly. Is this cable the proper cable?

DISCUSSION -----

The audio cable listed in the Service Price Pages is not correct. The proper cable part number is 590-4512.

Support Information Services  
Copyright 1995, Apple Computer, Inc.

Keywords: <None>

=====  
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 18982