



Tech Info Library

Macintosh Performa 6300: Which Drive to Order (2/96)

Article Created: 15 February 1996

Article Reviewed/Updated: 10 March 1997

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

Although all Macintosh Performa 6300 computers include a 1.2 GB hard drive, there are two different part numbers for these drives in the Apple Price Pages. How do I know which one to order to replace a customer's drive?

DISCUSSION -----

The distinguishing factor between the two drives is the manufacturer. Be sure to order the replacement drive from the same manufacturer as the one you remove: If you remove a Conner drive from the computer, order the replacement Conner mechanism; if you remove a Quantum drive, order the replacement Quantum drive.

661-1106: 1.2GB - Conner #CFS1275A

661-1139: 1.2GB - Quantum #FRBLA
1.2GB - Quantum #FBTMA
1.2GB - SeaGate #ST31276A

Article Change History:

10 Mar 1997 - Revised service part numbers.

Copyright 1996-97, Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

ArticleID: TECHINFO-0019354

19970311 09:04:17.00

Tech Info Library Article Number: 19354