



Tech Info Library

NuBus Cap Part Number Not On Service Source CD (5/95)

Article Created: 25 May 1995

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I have a customer who has removed a NuBus card from their Power Macintosh 8100. They want to cover up the hole it has left in the back panel, but they have lost the plastic cap.

I have looked on the Service Source CD, but I cannot find the part number for the NuBus cover. Do I have to order the whole back panel to get this little cover?

DISCUSSION -----

No, you do not have to order the whole back panel. The part you want is called a NuBus cap. The NuBus cap used on the Power Macintosh 8100 series of computers is the same part number as the NuBus cap for the Power Macintosh 7100 series computers and many others.

The Part number is 810-6035. This part number is used for all machines manufactured in several form factors including:

- Macintosh IIVx
- Macintosh Quadra 650
- Macintosh Quadra 800
- Macintosh Quadra 840AV
- Macintosh Quadra 900
- Macintosh Quadra 950
- Power Macintosh 7100
- Power Macintosh 8100
- Workgroup Server 9150

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: hts,kppc

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17812