



Tech Info Library

PowerBook 145: Repair Strategy (9/92)

Article Created: 2 September 1992

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

This article discusses the repair strategy for the Macintosh PowerBook 145.

DISCUSSION -----

The PowerBook 145 has two new parts, the display bezel and the expansion board (or daughterboard).

The PowerBook 145 expansion board is basically a PowerBook 170 expansion board without the 68882 math co-processor.

If a PowerBook 145 is returned for service, and it is determined that the expansion board is at fault, the PowerBook 145 expansion board will be replaced with a PowerBook 170 expansion board that includes the 68882 math co-processor.

If the expansion board is replaced, the "About This Macintosh ..." item in the Apple menu will show "PowerBook 170". Also, applications that use a math co-processor will have the use of the 68882.

All other parts are backward compatible.
Copyright 1992, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10653