



Tech Info Library

PowerBook 100: 40MB HDA Mounting Brackets

Article Created: 3 December 1992

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

Does the 40MB HDA Mounting Bracket for the PowerBook 100 (Service P/N 948-0157) consist of two pieces (one piece for each side of the hard drive), or a single piece?

Are the hard drive mounting screws provided with the bracket? If not, how can I get them?

DISCUSSION -----

There are two versions of the 2.5-inch 40MB hard drive for the PowerBook 100 (Service P/N 661-1644). These versions are functionally identical and differ only in thickness.

- One version is 18.8mm thick and uses Service P/N 948-0157 as its mounting bracket. This bracket is considered to be one bracket. It is, however, made up of two pieces -- one piece on each side of the hard drive.
- The other version is 15.6mm thick. This drive uses Service P/N 948-0002 as its mounting bracket.

The bracket screws (Service P/N 076-0557) are not provided with either bracket, and must be purchased separately.

Copyright 1992, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11034