



Tech Info Library

Power Macintosh: AV Card Revision Resolves Ghosting (10/94)

Article Created: 19 October 1994

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

Some Power Macintosh™ AV customers may notice light horizontal streaks or lines extending from the edges of windows or text when a monitor is attached to their Power Macintosh AV card. These horizontal lines appear to "ghost" or "smear" the video.

DISCUSSION -----

The ghosting effect may be present on a variety of monitors; however, it is most noticeable on the Apple 17-inch and 20-inch Multiple Scan monitors, as well as some third-party monitors.

To minimize the ghosting effect, a revision has been made to the Power Macintosh AV card. If a Power Macintosh AV system exhibits video ghosting or smearing, Service Providers should exchange the Power Macintosh AV card for the revised Power Macintosh AV card.

Apple Service Providers can order the revised Power Macintosh AV card (661-1023) through their normal service channels.

The revised cards can be identified by the "R" stamp after the vendor & datecode at the back of the board.

Example: V 94XX R

Support Information Services
Copyright 1994, Apple Computer, Inc.

Keywords: kppc

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16560