



Tech Info Library

PowerBook 280c: Battery Contact Alignment (9/95)

Article Created: 27 March 1995

Article Reviewed/Updated: 5 September 1995

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

Powerbook 280c Duo battery contacts can become misaligned when a unit is disassembled and reassembled.

DISCUSSION -----

Powerbook Duo computers with misaligned battery contacts will intermittently power off when using the battery. This is exasperated by using the Duo with the feet down or in a Mini Dock style dock.

Service providers can check the alignment of the battery contacts by using the Battery Contact Alignment Tool (part# 077-0085).

Article Change History:

05 Sep 1995 - Reviewed and updated format.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17436